

Gold/Silver Leaf Candles

Gold/Silver Leaf Candles



You Will Need:

Gel Wax
Gold/Silver Leaf
Old Saucepan
S/steel/silver spoon
Candy thermometer

Method:

Over a very low heat, melt gel wax like butter. Stir with stainless steel spoon.

Turn heat off when melted. Allow too cool slightly.

For gold /silver leaf candles, shred leaf and either drop into pot while pouring. Or use chunk method. Tear chunks of gel, arrange around wick, and sprinkle gold/silver leaf on to gel chunks and over pour with clear gel.

*To wick containers, cut wick, measure length holding next to container, allow 2-4cm extra. Thread thru tab, crimp tab with pliers. Place in container, place skewer along top of container, wrap extra length around.

If you have too many bubbles when gel has set, you can place in oven on the lowest setting to remelt and set. 1-3hrs. Keep on eye on it, once it has remelted, turn off and leave in oven too cool.

Candle Burning Instructions

1. Never burn a candle unattended.
2. Never burn for more than four hours at a time.
3. Always trim wick to 6mm above gel surface before use.
4. Never burn the last 1 inch of the candle.

Meldon CraftsAroma